

JAMESTOWN ARCH SHOULD BE REBUILT

THE MODERN HOUSE LACKS THE CHARACTER OF THE TRADITIONAL 'IRISH' - COTTAGE and SHOULD BLEND IN TO ITS ENVIRONMENT

...OUR COTTAGES WHY LET THEM GO?

WE COULD ENHANCE OUR STREETS BY PLANTING MORE NATIVE TREES

BOYLE

DUBLIN

SLIGO

MOHILL


CARRICK - ON - SHANNON

FLYNNAL

STOP Treeless

County Council 1990 Plan
JAMESTOWN ARCH

ROAD CLOSED



DIVIDED
SUPPER
MARKET
CHIPS
DUMP

LET'S SEE MORE
TRADITIONAL
SIGNS

DISUSED CHURCHES
CAN BE SUCCESSFULLY
CONVERTED -
... MUSEUMS /
ART GALLERY /
LIBRARY.

WHEN REDEVELOPMENT
TAKES PLACE, IT
IS IMPORTANT
THAT EXISTING
STREET LINE
ARE
ADHERED
TO.
(P. SHAFFER)

ROAD SIGNS, CRUDELY
POSITIONED, ARE
DIFFICULT TO
READ

WIRES AND POLES
POSITIONED WITHOUT
ANY AESTHETIC
CONSIDERATION.

PHONE BOXES
SHOULD BE
POSITIONED
WITH CARE
& THOUGHT
TO THE
FLOW OF
THE
STREET.

JEANETTE DUNNE 1990